

**REPORT CONTAMINACIÓN**

nº: 81580

**FACILITY NAME:** Rova Head Landfill Site

81581

**FacilityInspireID:** UK.SEPA/200002310.Facility**COUNTRY:** United Kingdom**CONTINENT:** EUROPE**CITY:** Lerwick**EPTRSectorCode:** 5 **eptrSectorName:** Waste and wastewater management**MainActivityCode:** 5(d)**targetRelease:** AIR **pollutant:** Methane (CH<sub>4</sub>)**emissions:** 227000**DAY:** 15 **MONTH:** 1 **YEAR:** 2019**METEOROLOGICAL CONDITIONS****max\_wind\_speed:** 1,41E+15 **min\_wind\_speed:** 2,17E+16 **avg\_wind\_speed:** 1,51E+16**max\_temp:** 3,97E+16 **min\_temp:** 6,06E+15 **avg\_temp:** 4,91E+15**DAYS FOG:** 3**REPORTER NAME** Leslie Baker**CITY\_ID** 218e50104ad214eb8a6c59b289c32667