

**REPORT CONTAMINACIÓN**

nº: 81592

**FACILITY NAME:** Dunbar Energy Recovery Facility

81593

**FacilityInspireID:** UK.SEPA/200002618.Facility**COUNTRY:** United Kingdom**CONTINENT:** EUROPE**CITY:** East Barns, Dunbar, East Lothian**EPTRSectorCode:** 5 **eptrSectorName:** Waste and wastewater management**MainActivityCode:** 5(b)**targetRelease:** AIR **pollutant:** Nitrogen oxides (NOX)**emissions:** 323000**DAY:** 11 **MONTH:** 10 **YEAR:** 2019**METEOROLOGICAL CONDITIONS****max\_wind\_speed:** 1,93E+16 **min\_wind\_speed:** 2,67E+15 **avg\_wind\_speed:** 1,87E+16**max\_temp:** 6,82E+15 **min\_temp:** 1,37E+16 **avg\_temp:** 8,77E+15**DAYS FOG:** 1**REPORTER NAME** Christopher Tate**CITY\_ID** 6935acf68ac33c9c85ff634275880d97