

REPORT CONTAMINACIÓN

nº: 81582

FACILITY NAME: Dalmacoulter Landfill Site
FacilityInspireID: UK.SEPA/200002314.Facility

81583

COUNTRY: United Kingdom**CONTINENT:** EUROPE**CITY:** Dalmacouter

EPTRSectorCode: 5 **eptrSectorName:** Waste and wastewater management

MainActivityCode: 5(d)

targetRelease: AIR **pollutant:** Methane (CH4)
emissions: 104000

DAY: 18 **MONTH:** 7 **YEAR:** 2019

METEOROLOGICAL CONDITIONS

max_wind_speed: 9,89E+15 **min_wind_speed:** 1,63E+16 **avg_wind_speed:** 1,52E+16

max_temp: 1,25E+16 **min_temp:** 1,75E+16 **avg_temp:** 1,48E+16

DAYS FOG: 5

REPORTER NAME Keith Holmes

CITY_ID 20b790f3c89efe9244f4b79071f3d7c5