REPORT CONTAMINACIÓN

nº: 81518

FACILITY NAME: Alloa Glass Factory 81519

FacilityInspireID: UK.SEPA/200000073.Facility

COUNTRY: United Kingdom CONTINENT: EUROPE

CITY: Alloa

EPRTRSectorCode: 3 **eprtrSectorName:** Mineral industry

MainActivityCode: 3(e)

targetRealase: AIR pollutant: Carbon dioxide (CO2)

emissions: 1,49E+08

DAY: 9 **MONTH:** 11 **YEAR:** 2019

METEOROLOGICAL CONDITIONS

max_wind_speed: 1,11E+16 min_wind_speed: 2,03E+16 avg_wind_speed: 1,6E+16

max_temp: -1,9E+16 min_temp: 4,07E+16 avg_temp: 1,33E+15

DAYS FOG: 4

REPORTER NAME Vicki Brown

CITY_ID 2cc8f54182c37b8907f534011ea01e6f