

**REPORT CONTAMINACIÓN**

nº: 81597

**FACILITY NAME:** Millerhill Recycling & Energy Recovery Centre**FacilityInspireID:** UK.SEPA/200002651.Facility**COUNTRY:** United Kingdom**CONTINENT:** EUROPE**CITY:** Millerhill, Dalkeith**EPTRSectorCode:** 5 **eptrSectorName:** Waste and wastewater management**MainActivityCode:** 5(b)**targetRelease:** AIR **pollutant:** Nitrogen oxides (NOX)**emissions:** 175000**DAY:** 12 **MONTH:** 6 **YEAR:** 2019**METEOROLOGICAL CONDITIONS****max\_wind\_speed:** 1,79E+15 **min\_wind\_speed:** 2,2E+16 **avg\_wind\_speed:** 2,04E+15**max\_temp:** 1,51E+16 **min\_temp:** 1,82E+15 **avg\_temp:** 1,71E+16**DAYS FOG:** 10**REPORTER NAME** William Nelson**CITY\_ID** c662b4b4d859a9c224b5ac0acf221748