

REPORT CONTAMINACIÓN

nº: 81524

FACILITY NAME: Binn Farm Landfill Site

81525

FacilityInspireID: UK.SEPA/200000085.Facility**COUNTRY:** United Kingdom**CONTINENT:** EUROPE**CITY:** Glenfarg**EPTRSectorCode:** 5 **eptrSectorName:** Waste and wastewater management**MainActivityCode:** 5(d)**targetRelease:** AIR **pollutant:** Methane (CH₄)**emissions:** 196000**DAY:** 7 **MONTH:** 6 **YEAR:** 2019**METEOROLOGICAL CONDITIONS****max_wind_speed:** 2,15E+15 **min_wind_speed:** 2,78E+16 **avg_wind_speed:** 2,08E+16**max_temp:** 1,22E+15 **min_temp:** 1,58E+16 **avg_temp:** 1,22E+14**DAYS FOG:** 8**REPORTER NAME** Tammy Williams**CITY_ID** 930b3f6a2b01ab9967c61d939efce973