

**REPORT CONTAMINACIÓN**

nº: 81537

**FACILITY NAME:** Easter Langlee Landfill Site, Galashiels

81538

**FacilityInspireID:** UK.SEPA/200000113.Facility**COUNTRY:** United Kingdom**CONTINENT:** EUROPE**CITY:** Galashiels**EPTRSectorCode:** 5 **eptrSectorName:** Waste and wastewater management**MainActivityCode:** 5(d)**targetRelease:** AIR **pollutant:** Methane (CH<sub>4</sub>)**emissions:** 296000**DAY:** 4 **MONTH:** 8 **YEAR:** 2019**METEOROLOGICAL CONDITIONS****max\_wind\_speed:** 1,53E+14 **min\_wind\_speed:** 2,69E+16 **avg\_wind\_speed:** 2,07E+15**max\_temp:** 1,65E+15 **min\_temp:** 2,02E+16 **avg\_temp:** 1,91E+16**DAYS FOG:** 7**REPORTER NAME** Ashley Villa**CITY\_ID** ff6f902129dcd065ed5a34da955999a7