

Move-In Condition Report

Prepared with DepositCam


Property	482 Maple Ave
Unit	Apt 3B
Landlord / Mgmt	Northside Property Group
Inspection type	Move-In
Date recorded	7/5/2026, 12:15:42 PM
Rooms documented	5
Photos	3

Each photo in this report carries a timestamp (and GPS coordinates where available) that was burned into the image at the moment of capture. This report documents the condition of the property as observed on the date above.

Living Room

Notes

Small scuff on the floor near the window was already present at move-in.



West wall, window and radiator — Jul 5, 2026, 12:15:42 PM • 41.88580, -87.62290

Kitchen


Notes

All appliances clean and working. Cabinet doors aligned.



Cabinets, counter and sink — Jul 5, 2026, 12:15:44 PM • 41.88580, -87.62290

Bathroom



Tub, vanity and tile in good condition — Jul 5, 2026, 12:15:46 PM • 41.88580, -87.62290