

LALA HARYDAL PARK — INFRASTRUCTURE

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: Lala Harydal Park, North Delhi (DDA)

Survey date: 19 May 2026, 11:49-12:12 IST (single-date baseline)

Category: Infrastructure

CATEGORY SCORE				
Indicator	Mean	Min	Max	Rating
Infrastructure	76.3%	29.6%	90%	Good

SCENE COVERAGE (park-wide mean)			
Metric	Mean	Min	Max
Paved area	0%	0%	0%

DETECTOR FINDINGS				
Detector class	Records	Mean cond. %	Worst %	Condition
Walking Track	178	54.7	29.6	Poor
Kerb / Edging	1092	84.8	73.1	Good
Bench	282	80.5	70.4	Good
Open Gym Equipment	331	79.3	58.7	Good
Pathway Obstruction	0	—	—	Not observed in these clips
Paved Area	100	78	72	Good
Excavation / Disturbed Ground	0	—	—	Not observed in these clips
Material Stockpile	0	—	—	Not observed in these clips
Construction Activity	0	—	—	Not observed in these clips

ANOMALIES (worst first)					
Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
10	Palm avenue & lawns	Walking Track	High	33.1	Resurface / patch the track; restore edge definition and camber.
53	Formal beds & pathways	Walking Track	High	42.2	Resurface / patch the track; restore edge definition and camber.
227	Formal beds & pathways	Walking Track	Medium	52.7	Resurface / patch the track; restore edge definition and camber.
327	Formal beds & pathways	Walking Track	Medium	59.8	Resurface / patch the track; restore edge definition and camber.

RECOMMENDED ACTIONS				
#	Priority	Finding	Recommended action	Owner

#	Priority	Finding	Recommended action	Owner
6	Low	Tree tree cover, topiary, kerbs, benches and paved avenues are all in reasonable condition.	Maintain the current regime for planting and hardscape; the investment needed is in the ground plane.	Horticulture Division
7	Process	Items recorded on site with no detector class yet: flower beds, weeds near pathways, water pipes and leakage, dustbins, gates, gazebo, signposts, streetlights, parking, boundary wall and railings as distinct classes.	Confirm which matter most for the DDA report and they can be added. Flower beds and weeds-near-pathways are both straightforward and directly relevant to this park.	Survey / Drone Cell
8	Process	The saturated-colour rule reports 681 play-equipment and 331 gym-equipment records in a park where none was observed - it is catching red benches and planter edging.	Treat those two rows as unverified. A scene-level gate similar to the one used for construction can suppress them per park on request.	Survey / Drone Cell

Generated from Lala_Hardeval_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 3 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.