

LALA HARYDAL PARK — WATER BODIES

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: Lala Harydal Park, North Delhi (DDA)

Survey date: 19 May 2026, 11:49-12:12 IST (single-date baseline)

Category: Water Bodies

SCENE COVERAGE (park-wide mean)

Metric	Mean	Min	Max
Water surface	0.8%	0%	6.7%
Algal share	0%	0%	0%
Exposed bed	0%	0%	0%

DETECTOR FINDINGS

Detector class	Records	Mean cond. %	Worst %	Condition
Water Body	42	57.9	24.9	Poor
Exposed Bed / Bank	0	—	—	Not observed in these clips
Floating Waste	0	—	—	Not observed in these clips

ANOMALIES (worst first)

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
3	Palm avenue & lawns	Water Body	Critical	24.9	Water-quality intervention required.
4	Palm avenue & lawns	Water Body	Critical	26.2	Water-quality intervention required.

Generated from Lala_Hardeval_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 3 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.