

R BLOCK, ASAF ALI PARK — ASSET INVENTORY

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: R Block, Asaf Ali Park, Asaf Ali Road (DDA)

Survey date: 18 May 2026, 12:16-12:35 IST (single-date baseline)

Category: Asset Inventory

DETECTOR FINDINGS				
Detector class	Records	Mean cond. %	Worst %	Condition
Tree Stem	1853	94.3	41.7	Good
Bench	161	79.8	70.5	Good
Play Equipment	429	79	68	Good
Open Gym Equipment	362	80.3	74.7	Good
Walking Track	310	55.6	32.2	Poor

ANOMALIES (worst first)					
Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
2	Pavilion (close-range)	Walking Track	High	36.4	Resurface / patch the track; restore edge definition and camber.
9	Pavilion (close-range)	Walking Track	High	40.6	Resurface / patch the track; restore edge definition and camber.
10	Pavilion (close-range)	Walking Track	High	41.5	Resurface / patch the track; restore edge definition and camber.
39	Pavilion (close-range)	Walking Track	Medium	57	Resurface / patch the track; restore edge definition and camber.
45	Pavilion (close-range)	Walking Track	Medium	58.7	Resurface / patch the track; restore edge definition and camber.
49	Garden & tree canopy	Tree Stem	Medium	59.6	Check stem for lean, cavities or decay; make safe if unstable.

Generated from Asaf_Ali_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 2 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.