

R BLOCK, ASAF ALI PARK — IRRIGATION STATUS

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: R Block, Asaf Ali Park, Asaf Ali Road (DDA)

Survey date: 18 May 2026, 12:16-12:35 IST (single-date baseline)

Category: Irrigation Status

CATEGORY SCORE				
Indicator	Mean	Min	Max	Rating
Irrigation Efficiency	78.7%	30.2%	98.1%	Good

SCENE COVERAGE (park-wide mean)			
Metric	Mean	Min	Max
Bare ground	13.5%	1.4%	51.1%
Dry vegetation	1.2%	0%	11.4%
Waterlogging	0.1%	0%	0.7%

DETECTOR FINDINGS				
Detector class	Records	Mean cond. %	Worst %	Condition
Waterlogging	0	—	—	Not observed in these clips
Bare Ground Patch	171	50.3	44.9	Poor
Dry / Dead Vegetation	306	49.5	41.2	Poor

ANOMALIES (worst first)					
Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
12	Pavilion (close-range)	Dry / Dead Vegetation	High	44.5	Clear dry and dead material; prune out deadwood and irrigate.
14	Garden & tree canopy	Bare Ground Patch	Medium	47.3	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
18	Pavilion (close-range)	Dry / Dead Vegetation	Medium	50.1	Clear dry and dead material; prune out deadwood and irrigate.
19	Pavilion (close-range)	Dry / Dead Vegetation	Medium	50.1	Clear dry and dead material; prune out deadwood and irrigate.
20	Pavilion (close-range)	Dry / Dead Vegetation	Medium	50.4	Clear dry and dead material; prune out deadwood and irrigate.
23	Pavilion (close-range)	Dry / Dead Vegetation	Medium	50.9	Clear dry and dead material; prune out deadwood and irrigate.
24	Pavilion (close-range)	Dry / Dead Vegetation	Medium	51.2	Clear dry and dead material; prune out deadwood and irrigate.
25	Pavilion (close-range)	Dry / Dead Vegetation	Medium	51.4	Clear dry and dead material; prune out deadwood and irrigate.
27	Garden & tree canopy	Bare Ground Patch	Medium	51.8	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
35	Garden & tree canopy	Bare Ground Patch	Medium	55.5	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
36	Garden & tree canopy	Bare Ground Patch	Medium	55.5	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.

RECOMMENDED ACTIONS

#	Priority	Finding	Recommended action	Owner
3	Medium	Ground around the pavilion is bare and hard-packed (27.7% of frame) with dry plant growth, in contrast to the healthy garden zone.	Reinstate ground cover in the pavilion surrounds; relieve compaction from foot traffic and provide a defined paved apron where desire lines have formed.	Horticulture Division
5	Low	The garden zone is in good condition - 75% green cover, healthy flowering tree cover and shrubs, watering score 93.5.	Maintain the current planting regime in this zone.	Horticulture Division
6	Process	The site record describes widespread dry patches and poor lawn across this park, but Clip 1 shows healthy planting and only 4.6% bare ground. The two clips do not cover the open lawn areas where those defects were observed.	Fly the open lawn and pathway areas of R Block to capture the dry-patch evidence; the current pair of clips under-represents the park's condition.	Survey / Drone Cell
8	Process	No class exists for the defects that matter most here: paint failure, damp staining, cracked render, dustbins, streetlights, water coolers, monuments, water pipes.	Paint and damp condition on vertical surfaces is a genuinely different problem from the ground-plane work done so far and would need its own approach. Confirm whether it is wanted.	Survey / Drone Cell

Generated from Asaf_Ali_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 2 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.