

R BLOCK, ASAF ALI PARK — SAFETY & SECURITY

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: R Block, Asaf Ali Park, Asaf Ali Road (DDA)

Survey date: 18 May 2026, 12:16-12:35 IST (single-date baseline)

Category: Safety & Security

CATEGORY SCORE				
Indicator	Mean	Min	Max	Rating
Safety	95.4%	68%	96%	Good

DETECTOR FINDINGS				
Detector class	Records	Mean cond. %	Worst %	Condition
Vehicle in Premises	4	60	60	Fair
Low-Visibility Zone	52	68.5	67.6	Fair
Construction Activity	0	—	—	Not observed in these clips
Excavation / Disturbed Ground	0	—	—	Not observed in these clips

ANOMALIES (worst first)					
Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
50	Pavilion (close-range)	Vehicle in Premises	Low	60	Verify authorisation; otherwise enforce the no-vehicle rule inside the green boundary.
53	Pavilion (close-range)	Low-Visibility Zone	Low	68.3	Low-visibility zone - schedule a ground or low-altitude patrol.
54	Garden & tree canopy	Low-Visibility Zone	Low	68.9	Low-visibility zone - schedule a ground or low-altitude patrol.
55	Garden & tree canopy	Low-Visibility Zone	Low	69.1	Low-visibility zone - schedule a ground or low-altitude patrol.

RECOMMENDED ACTIONS				
#	Priority	Finding	Recommended action	Owner
4	Medium	Vehicles were detected inside the park boundary.	Confirm whether the movements are allowed; otherwise enforce vehicle restrictions.	Security / Park Management

Generated from Asaf_Ali_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 2 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.