

DDA PARK, ROHINI — INFRASTRUCTURE

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: DDA Park, Rohini, Rohini (DDA)

Survey date: 20 May 2026, 12:12-12:43 IST (single-date baseline)

Category: Infrastructure

Category Score				
Indicator	Mean	Min	Max	Rating
Infrastructure	73.1%	49.1%	90%	Fair

Scene Coverage (park-wide mean)			
Metric	Mean	Min	Max
Paved area	0%	0%	0%

Detector Findings				
Detector class	Records	Mean cond. %	Worst %	Condition
Walking Track	126	62.9	49.1	Fair
Kerb / Edging	341	83.7	73.9	Good
Bench	96	80.8	71	Good
Open Gym Equipment	0	—	—	Not observed in these clips
Pathway Obstruction	0	—	—	Not observed in these clips
Paved Area	4	77.4	77.1	Good
Excavation / Disturbed Ground	0	—	—	Not observed in these clips
Material Stockpile	0	—	—	Not observed in these clips
Construction Activity	0	—	—	Not observed in these clips

Anomalies (worst first)					
Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
167	Algal channel & banks	Walking Track	Medium	54.6	Resurface / patch the track; restore edge definition and camber.
205	Algal channel & banks	Walking Track	Medium	57	Resurface / patch the track; restore edge definition and camber.
218	Algal channel & banks	Walking Track	Medium	59.6	Resurface / patch the track; restore edge definition and camber.

Recommended Actions				
#	Priority	Finding	Recommended action	Owner

#	Priority	Finding	Recommended action	Owner
6	Medium	facilities sits at 71-77 across all zones - the weakest spread of any park surveyed. Only 126 pathway and 96 bench records, and the gazebo is visibly weathered.	Survey the path network and built assets; the low detection counts suggest a fragmented and under-maintained network rather than a detector limitation.	Engineering / Works
7	Process	Several items on the site record are simply not in these three clips: the bridge, children's rides, the water fountain, the main gate, excavation tools and streetlights.	Fly those specific features. The current three clips are weighted heavily toward the water bodies and under-represent the built assets that the site record flags as poor.	Survey / Drone Cell

Generated from Rohini_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 3 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.