

SMRITI VAN MAYUR VIHAR — WATER BODIES

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: Smriti Van Mayur Vihar, Mayur Vihar (DDA)

Survey date: 19 May 2026, 16:54-17:35 IST (single-date baseline)

Category: Water Bodies

SCENE COVERAGE (park-wide mean)					
Metric		Mean	Min	Max	
Water surface		2.3%	0%	15.3%	
Algal share		0%	0%	0%	
Exposed bed		0%	0%	0%	

DETECTOR FINDINGS				
Detector class	Records	Mean cond. %	Worst %	Condition
Water Body	165	76.4	24.8	Good
Exposed Bed / Bank	50	50	36.7	Poor
Floating Waste	14	84.8	74.4	Good

ANOMALIES (worst first)					
Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
14	Flooded planting bed	Water Body	High	30.6	Field verification required.
15	Flooded planting bed	Water Body	High	31	Field verification required.
16	Flooded planting bed	Water Body	High	31.1	Field verification required.
28	Flooded planting bed	Exposed Bed / Bank	High	37.7	Stabilise the bank; prevent construction fines from entering the water body.
59	Flooded planting bed	Exposed Bed / Bank	High	44.3	Stabilise the bank; prevent construction fines from entering the water body.
161	Flooded planting bed	Exposed Bed / Bank	Medium	53.8	Stabilise the bank; prevent construction fines from entering the water body.
173	Flooded planting bed	Exposed Bed / Bank	Medium	54.7	Stabilise the bank; prevent construction fines from entering the water body.
193	Flooded planting bed	Exposed Bed / Bank	Medium	56.4	Stabilise the bank; prevent construction fines from entering the water body.

Generated from Smriti_Van_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 4 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.