

VASANT UDYAN — ASSET INVENTORY

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: Vasant Udyan, Vasant Kunj (DDA)

Survey date: 18 May 2026, 15:03-15:07 IST (single-date baseline)

Category: Asset Inventory

DETECTOR FINDINGS

Detector class	Records	Mean cond. %	Worst %	Condition
Tree Stem	1855	91.6	49.2	Good
Bench	160	77.1	70.1	Good
Play Equipment	203	82.6	72.7	Good
Open Gym Equipment	533	85	75.5	Good
Walking Track	393	59.3	36.6	Poor

ANOMALIES (worst first)

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
32	Pathways & tree belt	Walking Track	High	43.3	Resurface / patch the track; restore edge definition and camber.
35	Pathways & tree belt	Walking Track	High	44	Resurface / patch the track; restore edge definition and camber.
46	Pathways & tree belt	Walking Track	Medium	45.3	Resurface / patch the track; restore edge definition and camber.
47	Pathways & tree belt	Walking Track	Medium	45.3	Resurface / patch the track; restore edge definition and camber.
55	Pathways & tree belt	Walking Track	Medium	47.1	Resurface / patch the track; restore edge definition and camber.
83	Pathways & tree belt	Walking Track	Medium	51.2	Resurface / patch the track; restore edge definition and camber.
101	Children's play area	Walking Track	Medium	53.5	Resurface / patch the track; restore edge definition and camber.
107	Children's play area	Walking Track	Medium	56.1	Resurface / patch the track; restore edge definition and camber.
109	Pathways & tree belt	Walking Track	Medium	56.6	Resurface / patch the track; restore edge definition and camber.
111	Pathways & tree belt	Walking Track	Medium	57.8	Resurface / patch the track; restore edge definition and camber.
117	Children's play area	Walking Track	Medium	59.4	Resurface / patch the track; restore edge definition and camber.

RECOMMENDED ACTIONS

#	Priority	Finding	Recommended action	Owner
2	High	The site record notes a broken swing, broken tiles on gym equipment and getting worse signboard paint. The detector finds and scores the equipment but cannot itself assert structural damage.	Physically inspect every play and gym unit; use the anomaly register to prioritise the lowest paint-integrity scores. Make any broken unit safe immediately - this is a children's play area.	Engineering / Works

Generated from Vasant_Udyan_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 2 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.