

VASANT VATIKA — IRRIGATION STATUS

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: Vasant Vatika, Vasant Kunj (DDA)

Survey date: 18 May 2026, 16:05-16:08 IST (single-date baseline)

Category: Irrigation Status

CATEGORY SCORE				
Indicator	Mean	Min	Max	Rating
Irrigation Efficiency	62.1%	19.9%	99.8%	Fair

SCENE COVERAGE (park-wide mean)			
Metric	Mean	Min	Max
Bare ground	26.5%	0%	50%
Dry vegetation	0.6%	0%	2.6%
Waterlogging	1%	0%	3.2%

DETECTOR FINDINGS				
Detector class	Records	Mean cond. %	Worst %	Condition
Waterlogging	38	49.8	49.5	Poor
Bare Ground Patch	418	26.8	6	Critical
Dry / Dead Vegetation	160	51.3	50.7	Poor

ANOMALIES (worst first)					
Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
1	Open gym & hedge beds	Bare Ground Patch	Critical	6	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
2	Open gym & hedge beds	Bare Ground Patch	Critical	6	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
3	Open gym & hedge beds	Bare Ground Patch	Critical	6.8	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
4	Open gym & hedge beds	Bare Ground Patch	Critical	10.7	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
5	Open gym & hedge beds	Bare Ground Patch	Critical	14.3	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
6	Open gym & hedge beds	Bare Ground Patch	Critical	18.3	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
7	Open gym & hedge beds	Bare Ground Patch	Critical	22.3	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
8	Open gym & hedge beds	Bare Ground Patch	Critical	22.6	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
9	Open gym & hedge beds	Bare Ground Patch	Critical	27.9	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
12	Open gym & hedge beds	Bare Ground Patch	High	34.5	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
19	Open gym & hedge beds	Bare Ground Patch	High	37.6	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
37	Central lawn & avenue	Bare Ground Patch	High	42.4	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
65	Open gym & hedge beds	Waterlogging	Medium	49.7	Investigate drainage; standing water is a slip and mosquito-breeding risk.
66	Open gym & hedge beds	Waterlogging	Medium	49.8	Investigate drainage; standing water is a slip and mosquito-breeding risk.
75	Central lawn & avenue	Dry / Dead Vegetation	Medium	50.9	Clear dry and dead material; prune out deadwood and irrigate.
76	Open gym & hedge beds	Dry / Dead Vegetation	Medium	51	Clear dry and dead material; prune out deadwood and irrigate.
77	Open gym & hedge beds	Dry / Dead Vegetation	Medium	51	Clear dry and dead material; prune out deadwood and irrigate.
79	Central lawn & avenue	Dry / Dead Vegetation	Medium	51.2	Clear dry and dead material; prune out deadwood and irrigate.
80	Open gym & hedge beds	Dry / Dead Vegetation	Medium	51.2	Clear dry and dead material; prune out deadwood and irrigate.
81	Open gym & hedge beds	Dry / Dead Vegetation	Medium	51.2	Clear dry and dead material; prune out deadwood and irrigate.
82	Open gym & hedge beds	Dry / Dead Vegetation	Medium	51.2	Clear dry and dead material; prune out deadwood and irrigate.
83	Central lawn & avenue	Dry / Dead Vegetation	Medium	51.3	Clear dry and dead material; prune out deadwood and irrigate.
84	Central lawn & avenue	Dry / Dead Vegetation	Medium	51.3	Clear dry and dead material; prune out deadwood and irrigate.
85	Central lawn & avenue	Dry / Dead Vegetation	Medium	51.3	Clear dry and dead material; prune out deadwood and irrigate.
92	Fountain & formal garden	Bare Ground Patch	Medium	51.4	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
88	Central lawn & avenue	Dry / Dead Vegetation	Medium	51.4	Clear dry and dead material; prune out deadwood and irrigate.
86	Open gym & hedge beds	Dry / Dead Vegetation	Medium	51.4	Clear dry and dead material; prune out deadwood and irrigate.
87	Open gym & hedge beds	Dry / Dead Vegetation	Medium	51.4	Clear dry and dead material; prune out deadwood and irrigate.
89	Open gym & hedge beds	Dry / Dead Vegetation	Medium	51.4	Clear dry and dead material; prune out deadwood and irrigate.
91	Open gym & hedge beds	Bare Ground Patch	Medium	51.4	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
93	Open gym & hedge beds	Dry / Dead Vegetation	Medium	51.4	Clear dry and dead material; prune out deadwood and irrigate.

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
94	Open gym & hedge beds	Dry / Dead Vegetation	Medium	51.4	Clear dry and dead material; prune out deadwood and irrigate.
95	Open gym & hedge beds	Dry / Dead Vegetation	Medium	51.5	Clear dry and dead material; prune out deadwood and irrigate.
111	Fountain & formal garden	Bare Ground Patch	Medium	54.1	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
113	Open gym & hedge beds	Bare Ground Patch	Medium	54.2	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
116	Central lawn & avenue	Bare Ground Patch	Medium	54.6	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
124	Central lawn & avenue	Bare Ground Patch	Medium	55.2	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
133	Central lawn & avenue	Bare Ground Patch	Medium	55.6	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.

RECOMMENDED ACTIONS

#	Priority	Finding	Recommended action	Owner
1	High	The open gym zone has 43% bare ground and 6.3% lawn with an watering score of 39.1, while the rest of the park sits above 90. The failure is localised to the area around the equipment pad.	Extend the watering that works elsewhere in the park into the gym zone, then decompact and re-turf. Consider a defined hard or soft-surface apron around the equipment where foot traffic concentrates.	Horticulture / Engineering
6	Process	The site record describes a water body that is unclear with algae growth. These three clips show a clean, operating fountain and no algae signature.	Either the affected water body is elsewhere in the park and not covered by this footage, or the condition has changed. Worth a targeted flight to settle it.	Survey / Drone Cell
7	Process	No class exists for: gazebo, streetlight, dustbin, water pipes, boundary wall distinct from kerb, or dead trees as a class separate from dry plant growth.	Confirm which matter most for the DDA report and they can be added.	Survey / Drone Cell

Generated from Vasant_Vatika_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 3 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.