

VASANT VATIKA — WATER BODIES

Category export · AI Drone Survey · DDA / DTU parameter framework
Site: Vasant Vatika, Vasant Kunj (DDA)
Survey date: 18 May 2026, 16:05-16:08 IST (single-date baseline)
Category: Water Bodies

SCENE COVERAGE (park-wide mean)

Metric	Mean	Min	Max
Water surface	0.8%	0%	6.3%
Algal share	0%	0%	0%
Exposed bed	0%	0%	0%

DETECTOR FINDINGS

Detector class	Records	Mean cond. %	Worst %	Condition
Water Body	43	89.4	78.4	Good
Exposed Bed / Bank	26	55.7	54.7	Poor
Floating Waste	17	87	87	Good

ANOMALIES (worst first)

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
122	Fountain & formal garden	Exposed Bed / Bank	Medium	55	Assess recharge and de-silting; stabilise and re-profile the eroded bank.
136	Fountain & formal garden	Exposed Bed / Bank	Medium	55.9	Assess recharge and de-silting; stabilise and re-profile the eroded bank.
138	Fountain & formal garden	Exposed Bed / Bank	Medium	56.5	Assess recharge and de-silting; stabilise and re-profile the eroded bank.
171	Fountain & formal garden	Floating Waste	Low	87	Deploy surface skimming and clear the shoreline catchment.

RECOMMENDED ACTIONS

#	Priority	Finding	Recommended action	Owner
6	Process	The site record describes a water body that is unclear with algae growth. These three clips show a clean, operating fountain and no algae signature.	Either the affected water body is elsewhere in the park and not covered by this footage, or the condition has changed. Worth a targeted flight to settle it.	Survey / Drone Cell

Generated from Vasant_Vatika_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 3 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.