FAIL

NP

NL-GOLD

# 12 Harbour St / Unit 4

Property Condition v1 · Living smoke alarm · Inspector Maya Inspector · Reviewer Jon Reviewer

3 PASS | 1 FAIL | 1 FINDING | 75% PASS

## Meta

| | |
|---|---|
| Address | 12 Harbour St |
| Unit | 4 |
| Occupancy | tenanted |
| Meter reading | — |
| Meter photo | — |

## Entry / hallway

| | |
|---|---|
| Door | — |
| Locks | Pass |
| Smoke alarm | Fail |
| Smoke alarm photo | — |
| Carbon monoxide alarm | Pass |

## Kitchen

| | |
|---|---|
| Cabinets | — |
| Sink | — |
| Appliances | — |
| Kitchen notes | — |
| Kitchen photos | — |

## Living

| | |
|---|---|
| Walls | — |
| Flooring | — |
| Windows | — |
| Electrical outlets | — |

## Bedrooms

FAIL

| | |
|---|---|
| Bedroom name | Bedroom 1 |
| Condition | — |
| Smoke alarm | Pass |
| Detector photo | — |
| Furnishings | — |

## Bath

| | |
|---|---|
| Plumbing | — |
| Moisture | — |
| Exhaust | — |
| Wet-area photo | — |

## Exterior / utilities

| | |
|---|---|
| Exterior notes | — |
| Exterior photos | — |

## Signatures

| | |
|---|---|
| Inspector signature | — |
| Tenant acknowledgment | Acknowledged |
| Location | — |

## Findings (1)

### Life-safety device failed

HIGH · OPEN

Dust cap still on. No chirp.

Owner Building manager · due 2026-09-01 · smoke_alarm

## Evidence



Annotated evidence · 2026-08-31

## Signatures

Inspector signature

—

Tenant acknowledgment

Acknowledged

Demo snapshot. Not a regulated certificate.

Issued 2026-08-31 by Jon Reviewer. Verify IS-NLINE01.