




a**Diagnostic separation****b****Connected structural reference****c****Transport axis: drive controls penetration****d****Deposition axis: loading raises local blockage**