

VPF-T9R4-IDX-001 Delivery Index

t9_r4 - grid-storage cell cathode on the Chen2020 NMC811/graphite profile

Result: HONEST NEGATIVE (no candidate satisfies the full contract; nothing reported as passing)

VPF numbering list:

- VPF-T9R4-DS-001 design_spec (design specification, negative result)
- VPF-T9R4-BOM-001 bom (bill of materials, fixed stack + screening space)
- VPF-T9R4-DSH-001 datasheet (target vs measured, NOT ACHIEVED)
- VPF-T9R4-CALC-001 calc (decisive calculations)
- VPF-T9R4-DVPR-001 dvpr (verification plan & results)
- VPF-T9R4-DFMEA-001 dfmea (failure modes & effects)
- VPF-T9R4-IDX-001 delivery_index (this file)

Audit trail: runs/exp/t9_r4/log.jsonl (entry 0 criteria; plan; rounds 1-4 propose/funnel/
evaluate; final entry, verdict: negative). Simulation outputs under comp/ and cell/.

Report: runs/exp/t9_r4/report.html.