



NATIONAL DEVELOPMENT COMPLEX

Deputy Directorate General of Quality Control

High Energy Radiation Laboratory, 3E

TEST REPORT

Test Report No: TR (088)/HERL/22

Job Card No: JC (174)/HERL/22

Date: March 14, 2022

INDENTER'S DATA			
Name:	Muhammad Imran	Designation:	Research Associate
Group & Site:	IQA/ 3T	Directorate:	3DC-P
Organization:	NDC	Contact No:	051-9314087, Ext 209

GENERAL DATA			
Sample Name:	3D Carbon Rod (Misc)	ID No:	RD-19C
Sample Receive Date:	March 07, 2022	Test Date:	March 10, 2022
Geometrical Shape:	Cylindrical	Quantity:	01
		Material:	Carbon Composite
		Thickness:	230.5 mm

TEST DATA			
Test Type: General	Test Name: Radiography	Test Method: ASME V	Technique: SWSI
Radiation Source:	LINAC (DZ-9/3000)	Focal Spot: 2 mm	SFD: 343 cm
Qualification Standard:	NDC-CPS/Comp/QM/3DCarbon/CCC-01 (Rev:01)	Temperature: 24.9 °C	Humidity: 44 %
		IQI: ASTM E 1025 (3D-04)	Sensitivity: 1-1T

Image Acquisition Parameters:

- Detector Type: X-Ray Film Carestream AGFA D7.
- Processing Equipment: Automatic film processor M43lc Carestream.

Test Purpose: To check internal defects

Results:

- No internal defects has been detected in 3D Carbon rod.

Status: OK

Remarks:

- ID # is written with marker on 3D Carbon rod.
- 3D Carbon rod is sent for radiography in blank form, surface pitting/ porosity will be evaluated after final machining.
- These results apply only to the item tested as received and mentioned above.
- This test report shall not be reproduced except in full, without written approval of QC Directorate.

Test Performed by: Mr. Abdul Wadud. (STO)

M. Zaheer Abbas. HOD (TDM)

Verified by: Mr. Gohar Farooq, HOD (CT)

Contact No. 3268 & 3269

Reviewed By:

PD (RT-1):

Mr. Altaf Hussain

Approved by:

Dir. (NDT):

Syed Jaber Hussain Shah

HERL/FM/02, Issue 09 (03-04-17)

(End of report)