



WillyFastSolutions Telemetry Audit

AUTOMATED FLEET PREVENTIVE MAINTENANCE WARNING REPORT

SAFE OPERATING STATUS: This B2B asset is operating within its normal service parameters. Maintenance completed at **450.0 hours**. Inspection passed and certified for deployment.

Asset & Client Specifications

Client Company:	Company TEST1
Asset Name:	Montacargar de Prueba
Brand / Model:	Toyota 8ff
Serial Number:	123456
Service Date:	2026-09-09 00:26:59
Service Hours:	450.0 hrs
Inspector:	WillyFastSolutions Superadmin



Detailed Inspection Results & Photographic Evidence

[Routine] Engine / Hydraulic Oil Change — **PASSED / COMPLETED**

No photo evidence attached.

[Routine] Oil Filter Replacement — **PASSED / COMPLETED**

No photo evidence attached.

[Routine] Air Filter Replacement — **PASSED / COMPLETED**

No photo evidence attached.

[Safety] Batteries Connections & Charge — **FAILED / PENDING**

No photo evidence attached.

[Safety] Working Lights & Alarm Signals — **FAILED / PENDING**

No photo evidence attached.

[Safety] Horn & Backup Alert Check — **FAILED / PENDING**

No photo evidence attached.

[Safety] Ignition System & Controls — **FAILED / PENDING**

No photo evidence attached.

[Safety] Fuel Lines & Injection Check — **FAILED / PENDING**

No photo evidence attached.

[Safety] Tires & structural integrity check — **FAILED / PENDING**

No photo evidence attached.

Inspector Notes & Operational Remarks

Test 1

Authorized digital maintenance certificate generated by WillyFastSolutions Fleet Telemetry System.