


## Visual WTB Diagnosis Question

Analyze the wind turbine blade in the figure and reason logically to identify potential defects.



## Inspection Paradigms Shift



expert models

Meta data: {"id": 448, "image\_id":141, "category": None, "bbox":[ ], "area": None, "segmentation": [ ], "is\_crowd": 0}



closed-set  
task-specific

general MLLMs

Thinking: The figure shows a close-up view of the nacelle, the upper tower and the blade root of a wind turbine. Through carefully inspection, I don't find any defects in these sections.



Answer:  
*no defect*



coarse-grained

BladeLM (ours)

Thinking: By scanning it, I notice an irregular area indicates anomaly. Zoom in and mark for further detection.



Thinking: The discolored surface appears to be erosion rather than dirt because of the material loss in detail. And primary suspects are exposure to moisture and radiation.



Answer:  
*erosion*

