




Project Design, Management & Supervision Consultancy Services for Himachal Pradesh Rural Drinking Water Improvement & Livelihood Project (HPRDWILP) (ADB Loan No.4196-IND)





deo Conference through Google Meet on Semi Annual Reports & GESI Progress



Glimpses of Water Houses in Una District.



Glimpses of Water Tanks.





Mr. Raghbir Singh Karlupia (Social & Gender Expert) PDMSC discussed with Mr. Rajesh Sharma (Suprentendent Engineer) PMU, Mandi & Mr. Sanjay Acharya (Project Manager Cum Executive Engineer) PIU, Dharmshala on Gender Norms & Social Safeguard Compliance.




Interaction with participants during a Focus Group Discussion in village Halera Billna, District-Una.



Focus Group Discussion (FGD) Meeting at Village -Jhuggi, Block-Karsog, District-Mandi.

Site Inspection at WTP, Sundernagar, District-Mandi.





Interaction with Gram Pradhan & Contractor about livelihood generation & women labours issues.



Listen the Grievance raised by the Private Land Owner.

Mr. Raghbir Singh Karlupia (Social & Gender Expert) PDMSC along with, Miss Kusum Lata (Environment Officer) interact with participants during FGD at Mandi & Kullu District.



Grievance Meeting with Effected Families on Disputed Land.



Meeting with Three Panchayats on Conflict of Water Distribution at Sundernagar.



Mr. Raghbir Singh Karlupia (Social & Gender Expert) PDMSC Clear the Doubts & Queries raised by the participants of Three Gram Panchayats.



Joint Site Visit with Panchayat Members & Engineers to understand Scattered Population of the Area.

Site Inspection to Cross Check Compliance of Social Safeguard Norms.



Mr.Raghbir Singh Karlupia (Social & Gender Expert) PDMSC along with Mr. Jagjeet Singh (A.C.M), Ms. Anita Kumari (Social Mobilizer) and Mr. Rohit Kumar Jha (Social Safeguard Officer) inspect the project site.

Encouraged for the Women Participation & Gender Mainstreaming in Kullu & Dharmshala.



Explain the Project Benefits & Pipe Layout Plan in Dharamshala & Dalhousie.





Mr. Raghbir Singh Karlupia (Social and Gender Expert) PDMSC discussed the Social Safeguard Compliance Issues with Mr. Sanjay Acharaya (Project Manager-cum-Executive Engineer) PIU-Dharamshala.



Address to Student and Staff of Jamyang Choling Institute of Buddhist, Dharamshala & Local Community on importance of Gender Equality Disability & Social Inclusion (GEDSI).



Mr. Raghbir Singh Karlupia (Social & Gender Expert) along with Ms. Pallavi Obrol (SDE) PIU-Chamba done site Inspection at Dalhousie to cross check compliance of Social Safeguard & Gender Norms.



Interaction with labours & check Safety Equipments.



Check First Aid Kits at Project Site.



Check Labour Insurance & Licence Documents.



Inspection at Project Site Overview & Status of Civil Work

Attend Focus Group Discussion with local women & Gram Pradhan at village-Kasoli, Solan.



Women Participants Explained their bad experice due to shortage of Drinking Water.

Site Inspection at Village Sanawar, District-Solan.



Check First Aid Kit at Project Site.



Check Labor Attendance Register



Directions to Excavation Machine Operator

Interaction with Labours



Mr. Raghbir Singh Karlupia (Social and Gender Expert) PDMSC explained project benefits to participants & encouraged for active participation at Village Baddi, Solan.



Glimpses During Site Inspection at Barotiwala & Badi, District-Solan.



Interaction with Water Guard & Social Safeguard Officer on compliance of Safegaurd norms at Barotiwala Water Works.



Mr. Raghbir Singh Karlupia (Social & Gender Expert) PDMSC inspect Safety Measurements on Water Tank Construction Site at Baddi.



Discussion with Contractor at Badi about some disputes in villages regarding pipeline laydown.


Inspection at Maryog Project Site, District-Solan.



Meeting regarding conflict on water distribution of 3 Panchayats at District-Solan.



Project Site Inspection at Badha, District-Kullu.



Interaction with Labors & Understand their Concerns.



Directions Given to Site Engineer regarding Safety Measurements Compliance.



Interaction with Local People.



Explain the importance of PPE Kit uses.



**Review Meeting of Site Engineers (Contractor) for the Social Safeguard Compliance
at project sites District-Una.**




Directions are given to Deputy Project Manager (Contractor) for the Social Safeguard Compliance.



Meeting with Land Donor & Gram Pradhan.

Project Site Marking.

Land Inspection at various locations of District Hamirpur & Taking Consents from Land Donors.




Deliver Presentation on Gender Budgeting to Various Stakeholders.




Site Inspection at WTP, Sunder Nagar, District-Mandi.



Directions are given to Site Engineer for basic facilities for labours at project site.



Check Inventory, Attendance, Labour Licence & Labour Insurance papers.



Check First Aid Kit at Project Site.

Discussion with Executive Engineer, SDE, ACM & Contractor for strictly adhere the gender and Social Safeguard Norms at each project site.



Discussion with Patwari regarding land trasformation process in District-Mandi.

Site Inspection at Grid-MS-2, District-Mandi.




Meetings with PRI Members on Land Donations & Safeguard Issues at Una.



Meeting regarding Griviance Redressal of Land Donors.



Site Inspection at Various Project Site in District-Una.





Meeting with Land Donors at District-Bilaspur.



Site Inspection at Project Site, Baddi, District-Solan.



Site Inspection at Barotiwala, District-Solan.

Site Inspection at Maryog, District-Solan.




Giving Directions to Site Engineer / Junior Engineer for the Compliance of Social Safeguard Norms.



Site Inspection at Seobagh during Pipeline Laydown at Hawai Tank, District- Kullu.

Joint Visit with Patwari / ACM / Contractor at Neoli, Project Land Identification, Marking & FRA Clearance.



Aut, Himachal Pradesh, India
Aut, Himachal Pradesh 175121, India
Lat 31.83862°
Long 77.232203°
29/05/24 12:08 PM GMT +05:30



Kullu, Himachal Pradesh, India
R6VJ+FMG, Garsa Rd, Himachal Pradesh 175121, India
Lat 31.843289°
Long 77.229199°
29/05/24 12:06 PM GMT +05:30

GPS Map Camera



Aut, Himachal Pradesh, India
Aut, Himachal Pradesh 175121, India
Lat 31.838564°
Long 77.231908°
29/05/24 12:07 PM GMT +05:30



Directions are given to the Site Engineer regarding Safety Concerns & Interaction with the labours at Kholibar & Aut Project Site, District-Kullu.




Discussion with Project Manager & Contractor on compliance of Social Safeguard & Gender Norm issues at project site of MZ-01, Package at Kullu.

Site Inspection at Aut, District-Kullu and Check Site Register, GRC Register, First AID Kits and other relevant documents.



Site Inspection at Dalhousie, District-Chamba.



Inspection at Store & Check PPE Inventory.

Interaction with Labours.



Interaction with the Participants during a Focus Group discussion at Banikhet, District-Chamba.



Meeting with Contractor on Social Safeguard Compliance.

Meeting with Private Land Owner on Grievance raised by him at Project Site.



Check Layout Plan

Meeting with Project Engineers.




Check relevant Documents at Project Site, Karsog, District-Mandi.

Conduct Training Cum Workshop on Gender Budget, Gender Mainstreaming & Social Inclusion (GESI) Action Plan and Social Safeguard Compliance.




Site Inspection & Interaction with project Engineers & Labours.

Site Inspection at Raghunath Padhar Sumpwell, District-Mandi



Interaction with the Labours at Project Site.





Listen the Grievance raised by the local public and private land owner.




Interaction with community regarding Public Grievance.

Review Meeting with Contractor.



Interaction with School students at Village-Matlana.

Check Safety Compliance at Project Site in Solan.



Attended Focus Group Discussion at District-Kullu.



Interaction with community regarding Public Grievance.

Review Meeting with Contractor.



Check Safety Compliance at Project Site in District-Mandi.



Deliver presentation on GESI, Gender Budgeting & Social Safeguard Compliance at Dharamshala.



GESI Workshop at Dalhousie, District-Chamba.





Deliver Presentation on National Labour Norm's to Contractor.





Site Inspection at WTP Sundernagar, District-Mandi.



Site Visit at Banikhet, Dalhousie, District-Chamba.

Site Inspection at Chamera Dam, District- Chamba.




GESI Workshop at District-Kullu.



Site Inspection at Kotla Barog-WTP, District-Solan.



Site Visit at Sadhiana, District-Mandi.



Site Inspection at Raghunath WTP-District-Mandi.



Site Visit At Thural WTP, District-Dharmshala.



Project Site Inspection at WTP-Thral, Dharamshala, District-Kangra.



Site Inspection at DZ-02 Package, Palampur, District-Kangra.



Site Inspection at WTP-Pandoh, Dam, District-Kullu for check Social Safeguard Compliance.




Attended Public Grivenace Meeting at Village Amru Vashni, Baddi,disctrict-Solan.



Project Site Inspection at WTP-Shida, District-Kullu.



Public Grievances Meeting at WTP-Shida, District-Kullu.



Attended Public Dispute Meeting at Village Falan, District-Kullu.

