



# Project Design, Management & Supervision Consultancy Services for Himachal Pradesh Rural Drinking Water Improvement & Livelihood Project (HPRDWILP) (ADB Loan No.4196-IND)



## Video Conference through Google Meet on Semi Annual Reports & GESI Progress



## Glimpses of Water Houses in Una District.



## Glimpses of Water Tanks.





Mr. Raghbir Singh Karlupia (Social & Gender Expert) PDMSC discussed with Mr. Rajesh Sharma (Suprentendent Engineer) PMU, Mandi & Mr. Sanjay Acharya (Project Manager Cum Executive Engineer) PIU, Dharmshala on Gender Norms & Social Safeguard Compliance.




Interaction with participants during a Focus Group Discussion in village Halera Billna, District-Una.



Focus Group Discussion (FGD) Meeting at Village -Jhuggi, Block-Karsog, District-Mandi.

## Site Inspection at WTP, Sundernagar, District-Mandi.





**Interaction with Gram Pradhan & Contractor about livelihood generation & women labours issues.**



**Listen the Grievance raised by the Private Land Owner.**

**Mr. Raghbir Singh Karlupia (Social & Gender Expert) PDMSC along with, Miss Kusum Lata (Environment Officer) interact with participants during FGD at Mandi & Kullu District.**



## Grievance Meeting with Effected Families on Disputed Land.



## Meeting with Three Panchayats on Conflict of Water Distribution at Sundernagar.



**Mr. Raghbir Singh Karlupia (Social & Gender Expert) PDMSC Clear the Doubts & Queries raised by the participants of Three Gram Panchayats.**



**Joint Site Visit with Panchayat Members & Engineers to understand Scattered Population of the Area.**

## Site Inspection to Cross Check Compliance of Social Safeguard Norms.



**Mr.Raghbir Singh Karlupia (Social & Gender Expert) PDMSC along with Mr. Jagjeet Singh (A.C.M), Ms. Anita Kumari (Social Mobilizer) and Mr. Rohit Kumar Jha (Social Safeguard Officer) inspect the project site.**

## Encouraged for the Women Participation & Gender Mainstreaming in Kullu & Dharmshala.



## Explain the Project Benefits & Pipe Layout Plan in Dharamshala & Dalhousie.





**Mr. Raghbir Singh Karlupia (Social and Gender Expert) PDMSC discussed the Social Safeguard Compliance Issues with Mr. Sanjay Acharaya (Project Manager-cum-Executive Engineer) PIU-Dharamshala.**



**Site Visit of WTP Gaj Khad (DD-03)**

**Discussion on Proposed Site Map.**



**Balreh, Himachal Pradesh, India**  
Trail to Shri Gunna Devi Mandir, Naddi, Balreh, Himachal Pradesh 176216, India  
Lat 32.251255°  
Long 76.309372°  
27/02/24 04:14 PM GMT +05:30

**Address to Student and Staff of Jamyang Choling Institute of Buddhist, Dharamshala & Local Community on importance of Gender Equality Disability & Social Inclusion (GEDSI).**



**Mr. Raghbir Singh Karlupia (Social & Gender Expert) along with Ms. Pallavi Obrol (SDE) PIU-Chamba done site Inspection at Dalhousie to cross check compliance of Social Safeguard & Gender Norms.**



**Interaction with labours & check Safety Equipments.**



**Check First Aid Kits at Project Site.**



**Check Labour Insurance & Licence Documents.**



**Inspection at Project Site Overview & Status of Civil Work**

## **Attend Focus Group Discussion with local women & Gram Pradhan at village-Kasoli, Solan.**



**Women Participants Explained their bad experice due to shortage of Drinking Water.**

## Site Inspection at Village Sanawar, District-Solan.



**Check First Aid Kit at Project Site.**



**Check Labor Attendance Register**



**Instructed to Safety Officer.**



**Directions to Excavation Machine Operator**

**Interaction with Labours**



**Mr. Raghbir Singh Karlupia (Social and Gender Expert) PDMSC explained project benefits to participants & encouraged for active participation at Village Baddi, Solan.**



## Glimpses During Site Inspection at Barotiwala & Badi, District-Solan.



**Interaction with Water Guard & Social Safeguard Officer on compliance of Safegaurd norms at Barotiwala Water Works.**



**Mr. Raghbir Singh Karlupia (Social & Gender Expert) PDMSC inspect Safety Measurements on Water Tank Construction Site at Baddi.**



**Discussion with Contractor at Badi about some disputes in villages regarding pipeline laydown.**


## Inspection at Maryog Project Site, District-Solan.



## Meeting regarding conflict on water distribution of 3 Panchayats at District-Solan.



## Project Site Inspection at Badha, District-Kullu.



**Interaction with Labors & Understand their Concerns.**



**Directions Given to Site Engineer regarding Safety Measurements Compliance.**



**Interaction with Local People.**



**Explain the importance of PPE Kit uses.**



## Review Meeting of Site Engineers (Contractor) for the Social Safeguard Compliance at project sites District-Una.



**Directions are given to Deputy Project Manager (Contractor) for the Social Safeguard Compliance.**



**Meeting with Land Donor & Gram Pradhan.**

**Project Site Marking.**

## Land Inspection at various locations of District Hamirpur & Taking Consents from Land Donors.




## Deliver Presentation on Gender Budgeting to Various Stakeholders.




## Site Inspection at WTP, Sunder Nagar, District-Mandi.



Directions are given to Site Engineer for basic facilities for labours at project site.



Check Inventory, Attendance, Labour Licence & Labour Insurance papers.




Check First Aid Kit at Project Site.

**Discussion with Executive Engineer, SDE, ACM & Contractor for strictly adhere the gender and Social Safeguard Norms at each project site.**



**Discussion with Patwari regarding land trasformation process in District-Mandi.**

## Site Inspection at Grid-MS-2, District-Mandi.



## Meetings with PRI Members on Land Donations & Safeguard Issues at Una.



Meeting regarding Griviance Redressal of Land Donors.



## Site Inspection at Various Project Site in District-Una.



**Meeting with Land Donors at District-Bilaspur.**  
**Site Inspection at Project Site, Baddi, District-Solan.**



## Site Inspection at Barotiwala, District-Solan.



## **Site Inspection at Maryog, District-Solan.**



**Check Site GRC Register, First Aid Kits & Insurance Documents.**



**Giving Directions to Site Engineer / Junior Engineer for the Compliance of Social Safeguard Norms.**



**Site Inspection at Seobagh during Pipeline Laydown at Hawai Tank, District- Kullu.**

**Joint Visit with Patwari / ACM / Contractor at Neoli, Project Land Identification,  
Marking & FRA Clearance.**



**Directions are given to the Site Engineer regarding Safety Concerns & Interaction with the labours at Kholibar & Aut Project Site, District-Kullu.**




**Discussion with Project Manager & Contractor on compliance of Social Safeguard & Gender Norm issues at project site of MZ-01, Package at Kullu.**

**Site Inspection at Aut, District-Kullu and Check Site Register, GRC Register, First AID Kits and other relevant documents.**



### Site Inspection at Dalhousie, District-Chamba.




**Inspection at Store & Check PPE Inventory.**

**Interaction with Labours.**



**Interaction with the Participants during a Focus Group discussion at Banikhet, District-Chamba.**




**Check relevant Documents at Project Site, Karsog, District-Mandi.**

**Conduct Training Cum Workshop on Gender Budget, Gender Mainstreaming & Social Inclusion (GESI) Action Plan and Social Safeguard Compliance.**



## Site Inspection at Raghunath Padhar Sumpwell, District-Mandi



Interaction with the Labours at Project Site.





**Listen the Grievance raised by the local public and private land owner.**




**Interaction with community regarding Public Grievance.**

**Review Meeting with Contractor.**



**Interaction with School students at Village-Matlana.**

**Check Safety Compliance at Project Site in Solan.**



**Attended Focus Group Discussion at District-Kullu.**



**Interaction with community regarding Public Grievance.**

**Review Meeting with Contractor.**



**Check Safety Compliance at Project Site in District-Mandi.**



**Deliver presentation on GESI, Gender Budgeting & Social Safeguard Compliance at Dharamshala.**



**GESI Workshop at Dalhousie, District-Chamba.**





**Deliver Presentation on National Labour Norm's to Contractor.**





**Site Inspection at WTP Sundernagar, District-Mandi.**



**Site Visit at Banikhet, Dalhousie, District-Chamba.**

## Site Inspection at Chamera Dam, District- Chamba.



## GESI Workshop at District-Kullu.



### Site Inspection at Kotla Barog-WTP, District-Solan.



### Site Visit at Sadhiana, District-Mandi.



### Site Inspection at Raghnath WTP-District-Mandi.

