

DAMAGE PHOTO DOCUMENTATION

Claim Number: GD-2024-25392

Claimant: Hans Richter

Date of Photos: 2025-03-19

Damage Type: Glass Damage

Damaged Object: living room window pane

Location: 86150 Augsburg

PHOTO EVIDENCE:

Photo 1: Full view of the shattered living room window pane. Spider-web crack pattern visible across the entire pane.

Photo 2: Close-up of the point of impact on the living room window pane. Clear radial fracture lines emanating from center.

Photo 3: Glass fragments on the floor below the living room window pane. Safety concern documented.

Photo 4: The frame and mounting of the living room window pane showing condition for replacement assessment.

Photo 5: Temporary boarding/covering installed over the damaged living room window pane for security.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the living room window pane at the property of Hans Richter in Augsburg.

A stray ball from neighboring children struck the living room window pane, causing it to crack and partially shatter. The living room window pane is now a safety hazard and must be replaced immediately.

The damage was first discovered on 2025-03-17.

These photographs were taken on 2025-03-19 to document the current condition for insurance claim processing.

Assessment: The living room window pane requires complete replacement.

Documented by: Hans Richter