

DAMAGE PHOTO DOCUMENTATION

Claim Number: GD-2024-34845

Claimant: Petra Wolf

Date of Photos: 2025-12-31

Damage Type: Glass Damage

Damaged Object: bathroom mirror wall

Location: 65183 Wiesbaden

PHOTO EVIDENCE:

Photo 1: Full view of the shattered bathroom mirror wall. Spider-web crack pattern visible across the entire pane.

Photo 2: Close-up of the point of impact on the bathroom mirror wall. Clear radial fracture lines emanating from center.

Photo 3: Glass fragments on the floor below the bathroom mirror wall. Safety concern documented.

Photo 4: The frame and mounting of the bathroom mirror wall showing condition for replacement assessment.

Photo 5: Temporary boarding/covering installed over the damaged bathroom mirror wall for security.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the bathroom mirror wall at the property of Petra Wolf in Wiesbaden.

During a break-in attempt, the intruder smashed the bathroom mirror wall. While nothing was stolen, the bathroom mirror wall is completely destroyed. Police report has been filed (reference included).

The damage was first discovered on 2025-12-29.

These photographs were taken on 2025-12-31 to document the current condition for insurance claim processing.

Assessment: The bathroom mirror wall requires complete replacement.

Documented by: Petra Wolf