

DAMAGE PHOTO DOCUMENTATION

Claim Number: GD-2024-69595

Claimant: Peter Gruber

Date of Photos: 2024-03-23

Damage Type: Glass Damage

Damaged Object: skylight window

Location: 04109 Leipzig

PHOTO EVIDENCE:

Photo 1: Full view of the shattered skylight window. Spider-web crack pattern visible across the entire pane.

Photo 2: Close-up of the point of impact on the skylight window. Clear radial fracture lines emanating from center.

Photo 3: Glass fragments on the floor below the skylight window. Safety concern documented.

Photo 4: The frame and mounting of the skylight window showing condition for replacement assessment.

Photo 5: Temporary boarding/covering installed over the damaged skylight window for security.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the skylight window at the property of Peter Gruber in Leipzig.

During a break-in attempt, the intruder smashed the skylight window. While nothing was stolen, the skylight window is completely destroyed. Police report has been filed (reference included).

The damage was first discovered on 2024-03-23.

These photographs were taken on 2024-03-23 to document the current condition for insurance claim processing.

Assessment: The skylight window requires complete replacement.

Documented by: Peter Gruber