

DAMAGE PHOTO DOCUMENTATION

Claim Number: GD-2025-41053

Claimant: Markus Leitner

Date of Photos: 2025-05-22

Damage Type: Glass Damage

Damaged Object: skylight window

Location: 55116 Mainz

PHOTO EVIDENCE:

Photo 1: Full view of the shattered skylight window. Spider-web crack pattern visible across the entire pane.

Photo 2: Close-up of the point of impact on the skylight window. Clear radial fracture lines emanating from center.

Photo 3: Glass fragments on the floor below the skylight window. Safety concern documented.

Photo 4: The frame and mounting of the skylight window showing condition for replacement assessment.

Photo 5: Temporary boarding/covering installed over the damaged skylight window for security.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the skylight window at the property of Markus Leitner in Mainz.

A falling object from the floor above hit the skylight window, shattering it completely. The skylight window pieces have been safely removed. Urgent replacement is required for weather protection.

The damage was first discovered on 2025-05-22.

These photographs were taken on 2025-05-22 to document the current condition for insurance claim processing.

Assessment: The skylight window requires professional repair.

Documented by: Markus Leitner