

DAMAGE PHOTO DOCUMENTATION

Claim Number: GD-2025-62479

Claimant: Ingrid Huber

Date of Photos: 2025-01-10

Damage Type: Glass Damage

Damaged Object: shower glass door

Location: 45127 Essen

PHOTO EVIDENCE:

Photo 1: Full view of the shattered shower glass door. Spider-web crack pattern visible across the entire pane.

Photo 2: Close-up of the point of impact on the shower glass door. Clear radial fracture lines emanating from center.

Photo 3: Glass fragments on the floor below the shower glass door. Safety concern documented.

Photo 4: The frame and mounting of the shower glass door showing condition for replacement assessment.

Photo 5: Temporary boarding/covering installed over the damaged shower glass door for security.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the shower glass door at the property of Ingrid Huber in Essen.

A falling object from the floor above hit the shower glass door, shattering it completely. The shower glass door pieces have been safely removed. Urgent replacement is required for weather protection.

The damage was first discovered on 2025-01-07.

These photographs were taken on 2025-01-10 to document the current condition for insurance claim processing.

Assessment: The shower glass door requires complete replacement.

Documented by: Ingrid Huber