

DAMAGE PHOTO DOCUMENTATION

Claim Number: GD-2025-66775

Claimant: Andrea Wagner

Date of Photos: 2025-11-29

Damage Type: Glass Damage

Damaged Object: bathroom mirror wall

Location: 60311 Frankfurt

PHOTO EVIDENCE:

Photo 1: Full view of the shattered bathroom mirror wall. Spider-web crack pattern visible across the entire pane.

Photo 2: Close-up of the point of impact on the bathroom mirror wall. Clear radial fracture lines emanating from center.

Photo 3: Glass fragments on the floor below the bathroom mirror wall. Safety concern documented.

Photo 4: The frame and mounting of the bathroom mirror wall showing condition for replacement assessment.

Photo 5: Temporary boarding/covering installed over the damaged bathroom mirror wall for security.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the bathroom mirror wall at the property of Andrea Wagner in Frankfurt.

Unknown cause led to spontaneous breakage of the bathroom mirror wall. The tempered glass crumbled into small pieces. Building management confirms this is a known issue with this glass type in older installations.

The damage was first discovered on 2025-11-27.

These photographs were taken on 2025-11-29 to document the current condition for insurance claim processing.

Assessment: The bathroom mirror wall requires complete replacement.

Documented by: Andrea Wagner