

DAMAGE PHOTO DOCUMENTATION

Claim Number: GD-2025-74478

Claimant: Claudia Zimmermann

Date of Photos: 2025-03-26

Damage Type: Glass Damage

Damaged Object: bathroom mirror wall

Location: 76131 Karlsruhe

PHOTO EVIDENCE:

Photo 1: Full view of the shattered bathroom mirror wall. Spider-web crack pattern visible across the entire pane.

Photo 2: Close-up of the point of impact on the bathroom mirror wall. Clear radial fracture lines emanating from center.

Photo 3: Glass fragments on the floor below the bathroom mirror wall. Safety concern documented.

Photo 4: The frame and mounting of the bathroom mirror wall showing condition for replacement assessment.

Photo 5: Temporary boarding/covering installed over the damaged bathroom mirror wall for security.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the bathroom mirror wall at the property of Claudia Zimmermann in Karlsruhe.

A stray ball from neighboring children struck the bathroom mirror wall, causing it to crack and partially shatter. The bathroom mirror wall is now a safety hazard and must be replaced immediately.

The damage was first discovered on 2025-03-25.

These photographs were taken on 2025-03-26 to document the current condition for insurance claim processing.

Assessment: The bathroom mirror wall requires complete replacement.

Documented by: Claudia Zimmermann