

DAMAGE PHOTO DOCUMENTATION

Claim Number: GD-2025-77786

Claimant: Markus Leitner

Date of Photos: 2025-12-19

Damage Type: Glass Damage

Damaged Object: shop front window

Location: 55116 Mainz

PHOTO EVIDENCE:

Photo 1: Full view of the shattered shop front window. Spider-web crack pattern visible across the entire pane.

Photo 2: Close-up of the point of impact on the shop front window. Clear radial fracture lines emanating from center.

Photo 3: Glass fragments on the floor below the shop front window. Safety concern documented.

Photo 4: The frame and mounting of the shop front window showing condition for replacement assessment.

Photo 5: Temporary boarding/covering installed over the damaged shop front window for security.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the shop front window at the property of Markus Leitner in Mainz.

A falling object from the floor above hit the shop front window, shattering it completely. The shop front window pieces have been safely removed. Urgent replacement is required for weather protection.

The damage was first discovered on 2025-12-19.

These photographs were taken on 2025-12-19 to document the current condition for insurance claim processing.

Assessment: The shop front window requires complete replacement.

Documented by: Markus Leitner