

## DAMAGE PHOTO DOCUMENTATION

Claim Number: GD-2025-79767

Claimant: Claudia Zimmermann

Date of Photos: 2024-08-07

Damage Type: Glass Damage

Damaged Object: balcony glass door

Location: 76131 Karlsruhe

### PHOTO EVIDENCE:

Photo 1: Full view of the shattered balcony glass door. Spider-web crack pattern visible across the entire pane.

Photo 2: Close-up of the point of impact on the balcony glass door. Clear radial fracture lines emanating from center.

Photo 3: Glass fragments on the floor below the balcony glass door. Safety concern documented.

Photo 4: The frame and mounting of the balcony glass door showing condition for replacement assessment.

Photo 5: Temporary boarding/covering installed over the damaged balcony glass door for security.

### DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the balcony glass door at the property of Claudia Zimmermann in Karlsruhe.

Unknown cause led to spontaneous breakage of the balcony glass door. The tempered glass crumbled into small pieces. Building management confirms this is a known issue with this glass type in older installations.

The damage was first discovered on 2024-08-06.

These photographs were taken on 2024-08-07 to document the current condition for insurance claim processing.

Assessment: The balcony glass door requires complete replacement.

Documented by: Claudia Zimmermann