

DAMAGE PHOTO DOCUMENTATION

Claim Number: SD-2024-29929

Claimant: Markus Leitner

Date of Photos: 2025-10-17

Damage Type: Storm Damage

Damaged Object: terrace canopy

Location: 55116 Mainz

PHOTO EVIDENCE:

Photo 1: Overview of storm damage to the terrace canopy. Visible structural displacement and debris.

Photo 2: Close-up of the impact point where wind/debris struck the terrace canopy.

Photo 3: Fallen tree branch / debris that caused the damage to the terrace canopy.

Photo 4: Wide angle of the property showing overall storm damage context.

Photo 5: Detail of the terrace canopy showing cracks, breaks, and structural compromise.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the terrace canopy at the property of Markus Leitner in Mainz.

Tornado-like wind conditions caused the terrace canopy to collapse entirely. The structural integrity is compromised beyond repair. Emergency securing measures have been taken.

The damage was first discovered on 2025-10-14.

These photographs were taken on 2025-10-17 to document the current condition for insurance claim processing.

Assessment: The terrace canopy requires professional repair.

Documented by: Markus Leitner