

DAMAGE PHOTO DOCUMENTATION

Claim Number: SD-2024-62124

Claimant: Georg Braun

Date of Photos: 2024-02-06

Damage Type: Storm Damage

Damaged Object: chimney cap

Location: 68159 Mannheim

PHOTO EVIDENCE:

Photo 1: Overview of storm damage to the chimney cap. Visible structural displacement and debris.

Photo 2: Close-up of the impact point where wind/debris struck the chimney cap.

Photo 3: Fallen tree branch / debris that caused the damage to the chimney cap.

Photo 4: Wide angle of the property showing overall storm damage context.

Photo 5: Detail of the chimney cap showing cracks, breaks, and structural compromise.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the chimney cap at the property of Georg Braun in Mannheim.

Storm-force winds ripped the chimney cap from its mounting. The chimney cap landed in the neighbor's garden. No injuries reported but the property damage is substantial.

The damage was first discovered on 2024-02-03.

These photographs were taken on 2024-02-06 to document the current condition for insurance claim processing.

Assessment: The chimney cap requires complete replacement.

Documented by: Georg Braun