

DAMAGE PHOTO DOCUMENTATION

Claim Number: SD-2024-87638

Claimant: Peter Gruber

Date of Photos: 2024-06-09

Damage Type: Storm Damage

Damaged Object: solar panels

Location: 04109 Leipzig

PHOTO EVIDENCE:

Photo 1: Overview of storm damage to the solar panels. Visible structural displacement and debris.

Photo 2: Close-up of the impact point where wind/debris struck the solar panels.

Photo 3: Fallen tree branch / debris that caused the damage to the solar panels.

Photo 4: Wide angle of the property showing overall storm damage context.

Photo 5: Detail of the solar panels showing cracks, breaks, and structural compromise.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the solar panels at the property of Peter Gruber in Leipzig.

Hailstorm with golf-ball sized hail stones severely damaged the solar panels. Multiple impact marks and cracks are visible. A professional assessment confirms total replacement is needed.

The damage was first discovered on 2024-06-07.

These photographs were taken on 2024-06-09 to document the current condition for insurance claim processing.

Assessment: The solar panels requires complete replacement.

Documented by: Peter Gruber