

DAMAGE PHOTO DOCUMENTATION

Claim Number: SD-2024-99086

Claimant: Claudia Zimmermann

Date of Photos: 2025-04-25

Damage Type: Storm Damage

Damaged Object: solar panels

Location: 76131 Karlsruhe

PHOTO EVIDENCE:

Photo 1: Overview of storm damage to the solar panels. Visible structural displacement and debris.

Photo 2: Close-up of the impact point where wind/debris struck the solar panels.

Photo 3: Fallen tree branch / debris that caused the damage to the solar panels.

Photo 4: Wide angle of the property showing overall storm damage context.

Photo 5: Detail of the solar panels showing cracks, breaks, and structural compromise.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the solar panels at the property of Claudia Zimmermann in Karlsruhe.

Hailstorm with golf-ball sized hail stones severely damaged the solar panels. Multiple impact marks and cracks are visible. A professional assessment confirms total replacement is needed.

The damage was first discovered on 2025-04-22.

These photographs were taken on 2025-04-25 to document the current condition for insurance claim processing.

Assessment: The solar panels requires complete replacement.

Documented by: Claudia Zimmermann