

DAMAGE PHOTO DOCUMENTATION

Claim Number: SD-2025-10904

Claimant: Stefan Bauer

Date of Photos: 2024-06-02

Damage Type: Storm Damage

Damaged Object: balcony railing

Location: 90402 Nuremberg

PHOTO EVIDENCE:

Photo 1: Overview of storm damage to the balcony railing. Visible structural displacement and debris.

Photo 2: Close-up of the impact point where wind/debris struck the balcony railing.

Photo 3: Fallen tree branch / debris that caused the damage to the balcony railing.

Photo 4: Wide angle of the property showing overall storm damage context.

Photo 5: Detail of the balcony railing showing cracks, breaks, and structural compromise.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the balcony railing at the property of Stefan Bauer in Nuremberg.

Hailstorm with golf-ball sized hail stones severely damaged the balcony railing. Multiple impact marks and cracks are visible. A professional assessment confirms total replacement is needed.

The damage was first discovered on 2024-06-01.

These photographs were taken on 2024-06-02 to document the current condition for insurance claim processing.

Assessment: The balcony railing requires professional repair.

Documented by: Stefan Bauer