

DAMAGE PHOTO DOCUMENTATION

Claim Number: SD-2025-76817

Claimant: Peter Gruber

Date of Photos: 2024-06-16

Damage Type: Storm Damage

Damaged Object: roof tiles

Location: 04109 Leipzig

PHOTO EVIDENCE:

Photo 1: Overview of storm damage to the roof tiles. Visible structural displacement and debris.

Photo 2: Close-up of the impact point where wind/debris struck the roof tiles.

Photo 3: Fallen tree branch / debris that caused the damage to the roof tiles.

Photo 4: Wide angle of the property showing overall storm damage context.

Photo 5: Detail of the roof tiles showing cracks, breaks, and structural compromise.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the roof tiles at the property of Peter Gruber in Leipzig.

Severe storm with wind speeds exceeding 100 km/h tore off several roof tiles. Debris was scattered across the property. Temporary covering has been applied to prevent further water ingress.

The damage was first discovered on 2024-06-15.
These photographs were taken on 2024-06-16 to document the current condition for insurance claim processing.

Assessment: The roof tiles requires complete replacement.

Documented by: Peter Gruber