

DAMAGE PHOTO DOCUMENTATION

Claim Number: SD-2025-83522

Claimant: Thomas Mueller

Date of Photos: 2024-11-16

Damage Type: Storm Damage

Damaged Object: chimney cap

Location: 10115 Berlin

PHOTO EVIDENCE:

Photo 1: Overview of storm damage to the chimney cap. Visible structural displacement and debris.

Photo 2: Close-up of the impact point where wind/debris struck the chimney cap.

Photo 3: Fallen tree branch / debris that caused the damage to the chimney cap.

Photo 4: Wide angle of the property showing overall storm damage context.

Photo 5: Detail of the chimney cap showing cracks, breaks, and structural compromise.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the chimney cap at the property of Thomas Mueller in Berlin.

Hailstorm with golf-ball sized hail stones severely damaged the chimney cap. Multiple impact marks and cracks are visible. A professional assessment confirms total replacement is needed.

The damage was first discovered on 2024-11-13.

These photographs were taken on 2024-11-16 to document the current condition for insurance claim processing.

Assessment: The chimney cap requires complete replacement.

Documented by: Thomas Mueller