

DAMAGE PHOTO DOCUMENTATION

Claim Number: SD-2025-91216

Claimant: Thomas Mueller

Date of Photos: 2024-06-19

Damage Type: Storm Damage

Damaged Object: window shutters

Location: 10115 Berlin

PHOTO EVIDENCE:

Photo 1: Overview of storm damage to the window shutters. Visible structural displacement and debris.

Photo 2: Close-up of the impact point where wind/debris struck the window shutters.

Photo 3: Fallen tree branch / debris that caused the damage to the window shutters.

Photo 4: Wide angle of the property showing overall storm damage context.

Photo 5: Detail of the window shutters showing cracks, breaks, and structural compromise.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the window shutters at the property of Thomas Mueller in Berlin.

Storm-force winds ripped the window shutters from its mounting. The window shutters landed in the neighbor's garden. No injuries reported but the property damage is substantial.

The damage was first discovered on 2024-06-19.

These photographs were taken on 2024-06-19 to document the current condition for insurance claim processing.

Assessment: The window shutters requires complete replacement.

Documented by: Thomas Mueller