

DAMAGE PHOTO DOCUMENTATION

Claim Number: SD-2025-91639

Claimant: Ursula Berger

Date of Photos: 2025-11-25

Damage Type: Storm Damage

Damaged Object: garden shed

Location: 53111 Bonn

PHOTO EVIDENCE:

Photo 1: Overview of storm damage to the garden shed. Visible structural displacement and debris.

Photo 2: Close-up of the impact point where wind/debris struck the garden shed.

Photo 3: Fallen tree branch / debris that caused the damage to the garden shed.

Photo 4: Wide angle of the property showing overall storm damage context.

Photo 5: Detail of the garden shed showing cracks, breaks, and structural compromise.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the garden shed at the property of Ursula Berger in Bonn.

Tornado-like wind conditions caused the garden shed to collapse entirely. The structural integrity is compromised beyond repair. Emergency securing measures have been taken.

The damage was first discovered on 2025-11-25.

These photographs were taken on 2025-11-25 to document the current condition for insurance claim processing.

Assessment: The garden shed requires complete replacement.

Documented by: Ursula Berger