

DAMAGE PHOTO DOCUMENTATION

Claim Number: WD-2024-12909

Claimant: Maria Schmidt

Date of Photos: 2025-05-13

Damage Type: Water Damage

Damaged Object: hallway ceiling

Location: 80331 Munich

PHOTO EVIDENCE:

Photo 1: Overview of the damaged hallway ceiling showing water stain patterns and discoloration across the entire surface.

Photo 2: Close-up of the burst/leaking pipe connection point. Visible corrosion and water residue around the joint.

Photo 3: Detail shot of water damage to the hallway ceiling showing material swelling and deformation.

Photo 4: Wide angle view showing the extent of flooding and water marks on surrounding walls.

Photo 5: Moisture meter reading on the hallway ceiling surface showing elevated humidity levels.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the hallway ceiling at the property of Maria Schmidt in Munich.

A corroded copper pipe in the wall burst during freezing temperatures. The resulting water leak damaged the hallway ceiling significantly. Drying equipment has been installed.

The damage was first discovered on 2025-05-12.

These photographs were taken on 2025-05-13 to document the current condition for insurance claim processing.

Assessment: The hallway ceiling requires complete replacement.

Documented by: Maria Schmidt