

DAMAGE PHOTO DOCUMENTATION

Claim Number: WD-2024-33045

Claimant: Ursula Berger

Date of Photos: 2025-05-13

Damage Type: Water Damage

Damaged Object: laundry room floor

Location: 53111 Bonn

PHOTO EVIDENCE:

Photo 1: Overview of the damaged laundry room floor showing water stain patterns and discoloration across the entire surface.

Photo 2: Close-up of the burst/leaking pipe connection point. Visible corrosion and water residue around the joint.

Photo 3: Detail shot of water damage to the laundry room floor showing material swelling and deformation.

Photo 4: Wide angle view showing the extent of flooding and water marks on surrounding walls.

Photo 5: Moisture meter reading on the laundry room floor surface showing elevated humidity levels.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the laundry room floor at the property of Ursula Berger in Bonn.

The washing machine supply hose ruptured overnight. Approximately 200 liters of water flooded the area, causing severe damage to the laundry room floor. Emergency plumber was called to stop the leak.

The damage was first discovered on 2025-05-12.

These photographs were taken on 2025-05-13 to document the current condition for insurance claim processing.

Assessment: The laundry room floor requires professional repair.

Documented by: Ursula Berger