

DAMAGE PHOTO DOCUMENTATION

Claim Number: WD-2024-49237

Claimant: Maria Schmidt

Date of Photos: 2025-08-08

Damage Type: Water Damage

Damaged Object: utility room walls

Location: 80331 Munich

PHOTO EVIDENCE:

Photo 1: Overview of the damaged utility room walls showing water stain patterns and discoloration across the entire surface.

Photo 2: Close-up of the burst/leaking pipe connection point. Visible corrosion and water residue around the joint.

Photo 3: Detail shot of water damage to the utility room walls showing material swelling and deformation.

Photo 4: Wide angle view showing the extent of flooding and water marks on surrounding walls.

Photo 5: Moisture meter reading on the utility room walls surface showing elevated humidity levels.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the utility room walls at the property of Maria Schmidt in Munich.

Toilet overflow due to a blocked drain caused water to spread across the floor. The utility room walls absorbed water and now shows buckling and staining. Immediate replacement is needed.

The damage was first discovered on 2025-08-08.

These photographs were taken on 2025-08-08 to document the current condition for insurance claim processing.

Assessment: The utility room walls requires complete replacement.

Documented by: Maria Schmidt