

DAMAGE PHOTO DOCUMENTATION

Claim Number: WD-2024-75590

Claimant: Hans Richter

Date of Photos: 2024-03-13

Damage Type: Water Damage

Damaged Object: bedroom carpet

Location: 86150 Augsburg

PHOTO EVIDENCE:

Photo 1: Overview of the damaged bedroom carpet showing water stain patterns and discoloration across the entire surface.

Photo 2: Close-up of the burst/leaking pipe connection point. Visible corrosion and water residue around the joint.

Photo 3: Detail shot of water damage to the bedroom carpet showing material swelling and deformation.

Photo 4: Wide angle view showing the extent of flooding and water marks on surrounding walls.

Photo 5: Moisture meter reading on the bedroom carpet surface showing elevated humidity levels.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the bedroom carpet at the property of Hans Richter in Augsburg.

A corroded copper pipe in the wall burst during freezing temperatures. The resulting water leak damaged the bedroom carpet significantly. Drying equipment has been installed.

The damage was first discovered on 2024-03-12.

These photographs were taken on 2024-03-13 to document the current condition for insurance claim processing.

Assessment: The bedroom carpet requires complete replacement.

Documented by: Hans Richter