

DAMAGE PHOTO DOCUMENTATION

Claim Number: WD-2025-18506

Claimant: Michael Becker

Date of Photos: 2024-01-04

Damage Type: Water Damage

Damaged Object: hallway ceiling

Location: 50667 Cologne

PHOTO EVIDENCE:

Photo 1: Overview of the damaged hallway ceiling showing water stain patterns and discoloration across the entire surface.

Photo 2: Close-up of the burst/leaking pipe connection point. Visible corrosion and water residue around the joint.

Photo 3: Detail shot of water damage to the hallway ceiling showing material swelling and deformation.

Photo 4: Wide angle view showing the extent of flooding and water marks on surrounding walls.

Photo 5: Moisture meter reading on the hallway ceiling surface showing elevated humidity levels.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the hallway ceiling at the property of Michael Becker in Cologne.

Leaking dishwasher connection caused slow water damage over several weeks. The hallway ceiling shows extensive water damage including swelling and discoloration. Professional repair is required.

The damage was first discovered on 2024-01-04.

These photographs were taken on 2024-01-04 to document the current condition for insurance claim processing.

Assessment: The hallway ceiling requires complete replacement.

Documented by: Michael Becker