

DAMAGE PHOTO DOCUMENTATION

Claim Number: WD-2025-80329

Claimant: Wolfgang Fischer

Date of Photos: 2025-05-02

Damage Type: Water Damage

Damaged Object: bathroom walls

Location: 44135 Dortmund

PHOTO EVIDENCE:

Photo 1: Overview of the damaged bathroom walls showing water stain patterns and discoloration across the entire surface.

Photo 2: Close-up of the burst/leaking pipe connection point. Visible corrosion and water residue around the joint.

Photo 3: Detail shot of water damage to the bathroom walls showing material swelling and deformation.

Photo 4: Wide angle view showing the extent of flooding and water marks on surrounding walls.

Photo 5: Moisture meter reading on the bathroom walls surface showing elevated humidity levels.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the bathroom walls at the property of Wolfgang Fischer in Dortmund.

A burst pipe in the bathroom caused extensive flooding. Water seeped through the floor and damaged the bathroom walls below. The bathroom walls shows visible water stains, warping, and mold formation.

The damage was first discovered on 2025-05-01.

These photographs were taken on 2025-05-02 to document the current condition for insurance claim processing.

Assessment: The bathroom walls requires professional repair.

Documented by: Wolfgang Fischer